


GEKONORM NM

Characteristic curves

Characteristic curves NM (n = 1450 rpm, 50 Hz)



Characteristic curves NM (n = 2900 rpm, 50 Hz)

